

John Deere Part - the easy part!



Worn out joint shafts? With the Front Axle Repair Sleeves from John Deere easily rectified!



Front Axle APL 345/350/735

AL71257

Front Axle APL 315/325

AL71299

Worn out universal joint shafts can cause leaking front axles. To avoid changing the whole universal joint use the John Deere front axle repair sleeves to seal the universal joint shaft and ensure the reliable operation of your tractor.



ONE kit - HIGH use



- a simple and effective solution
- peace of mind for reliable operation
- prevention of consequential damages
- a cost efficient method of repair without the need to change the whole universal joint shaft